


Installation instructions (double) interface cable

KERN CFS-A04

Version 1.0

08/2012

GB



CFS-A04-IA-e-1210



KERN CFS-A04

Version 1.0 08/2012

Installation instructions

Interface cable

1 Assembly

Connect the interface cable as shown in the drawing (pay attention to the marking of the cables!)



- 1 Connection of scale
- 2 Connection of printer/PC
- 3 Connection of signalling lamp

2 Technical details

- Cable length 150 cm
- Net weight 80 g
- It is suitable to:
KFB-TM, IFB, BFB, UFB, CFS, GAB-N, CPB-N, PFB, SFB, KFN-TM