



KERN & Sohn GmbH

Ziegelei 1
D-72336 Balingen
E-Mail: info@kern-sohn.com

Phone: +49-[0]7433-9933-0
Fax: +49-[0]7433-9933-149
Internet: www.kern-sohn.com

Installation Instructions Interface

KERN KFN-A01

Version 1.1
02/2013
GB

KFN-A01-IA-e-1311




KERN KFN-A01

Installation Instructions Interface

Assembly of the interface KFN-A01 in the terminal KFN-TM



Remove the screws on the backside of the terminal




Removing the cover




Guide the interface cable through the opening of the terminal



Screw down cable on the terminal





Plug cable into the RS-232 board




Plug RS-232 board into main board

Watch for pin allocation!





Tighten screw with spacer



Retighten screws on the back



Plug cable (1,5 m) for printer/PC together and lock it